

Summary of Preliminary Assessment on Structural, Fire and Electrical Safety

Name of the Factory : Alauddin & Son's (Pvt.) Ltd.
Address of the Factory : 120, East Tejturi Bazar, Tejgaon, Dhaka-1215
Present Status of the Factory : Under Operation
Structural Assessment Conducted by : BUET
Date of Structural Inspection : 1st January 2014

BASIC INFORMATION:

The Alauddin & Son's (Pvt.) Ltd. and Gold Star Design Ltd. factory building is a six storied RC frame building. The following information was noted:

- i. Building Usage Type : Mixed occupancy. Shops & store in GF and garment factories in upper floors
- ii. Structural System : RC frame building (beam-column framing)
- iii. Floor System : RC beam supported slabs
- iv. Floor Area : Approximately 9500 sft per floor (as reported)
- v. No. of Stories : Six storied
- vi. Construction Year : 1969-1990
- vii. Foundation Type : Individual footing on top of 16ft wooden pile (as per drawing)
- viii. Design Drawings : Available
- ix. Soil Boring Report : Available (done in May 2013)
- x. Construction Materials : Reinforced Concrete
- xi. Generator : In GF

RECOMMENDATIONS FOR CORRECTIVE ACTION:

The recommendations of corrective action for both Structural and Fire & Electrical Safety comprises in Short Term, Mid Term and Long Term basis.

The recommendations for **Structural Safety** corrective action are:

- Short Term (Immediate) : Average live load is to be limited to 60 psf (3 kN/m²) on all floors.
Mid Term (6-weeks) : None
Long Term (6-months) : None

Name of the Factory : Alauddin & Son's (Pvt.) Ltd.
Fire & Electrical assessment conducted by : BUET
Date of Fire & Electrical Inspection : 19 January 2014

Summary of Preliminary Assessment on Structural, Fire and Electrical Safety

(A): Recommendations for Fire Safety corrective actions:

<p>Immediate</p> <p><i>(the factory should not continue to be occupied until these non-conformities have been rectified):</i></p>	<p>N/A</p>
<p>Short Term</p> <p><i>(Actions that must be incorporated into a Fire Safety Management Plan immediately (a week) and should be a regular activity</i></p>	<p>Remove all temporary obstructions from all escape routes, aisles and passageways.</p> <p>Remove all combustible materials from generator room.</p> <p>Ensure minimum width of corridors, passageways and aisles.</p> <p>Ensure easy access to portable extinguishers and monitor and maintain the same at required interval as per guidelines.</p> <p>Provide proper directional sign and exit sign in Bangla and English as per guidelines</p>
<p>Mid Term</p> <p><i>(The remedial works indicated must be carried out within a period of 6 weeks)</i></p>	<p>Remove temporary structure from roof top.</p> <p>Produce proper drawing and plans to create horizontal and vertical fire-rated separation for stairways of appropriate specifications, grills, storage and assembly areas, basement, offices, work areas. Also design to ensure proper separation of high risk areas (e.g., generator, boiler, transformer and substation rooms) as per guidelines.</p> <p>Remove all collapsible gates. Produce design drawings to demonstrate how stairways are to be made of adequate dimensions and appropriate specifications and to be converted into fire-rated enclosures equipped with fire-rated side swinging doors of required dimensions opening in the direction of travel at each floor.</p> <p>Produce design to install standard standpipe, hose and fire pump system.</p> <p>Provide design to install proper detection and alarm system.</p>
<p>Long Term</p> <p><i>(The remedial works indicated must be carried out within a period of 6 months)</i></p>	<p>Install horizontal and vertical fire-rated separation for stairways, grills, storage and assembly areas, basement, offices, work areas.</p> <p>Ensure proper fire separation of high risk (e.g., generator, boiler, transformer and substation rooms) as per approved design</p> <p>Install fire rated enclosure and doors at exit to the stairs to prevent smoke and fire propagation as per approved design</p> <p>Install standard standpipe, hose and fire pump system.</p> <p>Install proper detection and alarm system.</p> <p>Provide fire rated enclosure, install self closing fire rated</p>

Summary of Preliminary Assessment on Structural, Fire and Electrical Safety

	door as per guidelines.
--	-------------------------

(B): Recommendations for Electrical Safety corrective actions:

<p>Immediate</p> <p><i>(the factory should not continue to be occupied until these non-conformities have been rectified):</i></p>	N/A
<p>Short Term</p> <p><i>(Actions that must be incorporated into a Fire Safety Management Plan immediately(a week) and should be a regular activity</i></p>	<p>Ensure well-dressed cabling with lugs and remove loose cabling.</p> <p>Ensure earthing of panel body & door with fitted condition.</p> <p>Provide distribution board as per guideline and put identification mark on distribution panel.</p> <p>Remove broken/loose MCB/MCCB box/socket</p>
<p>Mid Term</p> <p><i>(The remedial works indicated must be carried out within a period of 6 weeks)</i></p>	<p>Provide separate service ducts for electrical cables.</p> <p>Provide new Emergency Lighting system</p> <p>Provide appropriate Lightening Protection System as per guidelines</p>
<p>Long Term</p> <p><i>(The remedial works indicated must be carried out within a period of 6 months)</i></p>	. N/A