

Summary of Preliminary Assessment on Structural, Fire and Electrical Safety

Name of the Factory	: AZMAIN FASHION LTD.
Address of the Factory	: 791, Askarabad, Dhaka Trunk Road, Chittagong, Bangladesh.
Present Status of the Factory	: Under Operation.
Structural Assessment Conducted by	: VEC
Date of Structural Inspection	: 4 th July, 2015
Fire Assessment Conducted by	: VEC
Date of Fire Inspection	: 4 th July, 2015
Electrical Assessment Conducted by	: VEC
Date of Electrical Inspection	: 4 th July, 2015
BKMEA Membership No.	: 1959

BASIC INFORMATION:

The assessed factory building is 4 storied RCC beam column frame structure and there is a non-engineered shed over 4th floor covering 75% of floor area over RCC column. AZMAIN FASHION LTD. is occupied only on 2nd floor. Other floors are occupied by other RMG factories and market. The following general information was noted:

i. Building Usage Type	: Garment Factory.
ii. Structural System	: RCC beam column frame system.
iii. Floor System	: RCC beam slab floor system.
iv. Floor Area	: Total floor area is 34,500 sft.
v. No. of Stories	: 5-Storey. (4 Storey RCC + Shed)
vi. Construction Year	: In phase. (1982 and 2000)
vii. Foundation Type	: Unknown.
viii. Design Drawings	: Available document: Approval plan. Not available- Architectural drawing, structural drawing, machine layout plan, floor load plan, material test report has not been found.
ix. Soil Investigation Report	: Available.
x. Construction Materials	: Brick Aggregate (In column).
xi. Generator	: Outside of the building.

RECOMMENDATIONS FOR CORRECTIVE ACTION:

The recommendations of corrective action for both Structural and Fire & Electrical Safety comprises in Short Term, Mid Term and Long Term basis.

The recommendations for **Structural Safety** corrective action are:

Short Term (Immediate)	: None.
Mid Term (6-weeks)	: <ul style="list-style-type: none">• Factory Engineer to review design loads and column stresses in the areas identified above.• Verify in situ concrete stresses either by cores (100mm diameter) or existing cylinder strength data for all the columns or cores from a minimum of 4 non-critical columns.

Summary of Preliminary Assessment on Structural, Fire and Electrical Safety

- Produce and actively manage a loading plan for all floor plates within the factory giving consideration to floor capacity and column capacity.

Long Term (6-months)

:

- Develop set of as-built drawings showing structure details, loading, dimensions, levels, foundations and framing on Plan, Section and Elevation drawings.

The recommendations for **Fire & Electrical Safety** corrective action are:

(A): Recommendations for Fire Safety corrective actions:

<p>Immediate</p> <p><i>(the factory should not continue to be occupied until these non-conformities have been rectified):</i></p>	<ul style="list-style-type: none"> • Factory needs to ensure unobstructed means of escape i.e. aisles, exits, stairs.
<p>Short Term</p> <p><i>(Actions that must be incorporated into a Fire Safety Management Plan immediately (1 ~ 2 weeks) and should be a regular activity</i></p>	<ul style="list-style-type: none"> • Fire drill shall be conducted quarterly (4 times a year) under the Fire Safety Plan. A record of such drills shall be kept in writing for at least 3 years for the inspection of fire brigade whenever called for. • Factory need to have proper testing plan & record of fire safety equipment. • Factory needs to have marked aisles in all working floor according to 0.9m for one side seat and 1.0m for both side seat. • Lights in storage area are needed to be installed with protective covers and conduits. • Combustibles are to be managed with good housekeeping. Storage facilities with no air-conditioning duct shall be minimum 2.9 m and when used as a storage facility there shall be a minimum clearance of one third the floor height from the ceiling to the top of the storage stack. • Factory needs to close all the opening in the rated wall of the stair case by 2 hours rated construction/enclosure or 1.5 hours rated doors. • All required means of exit or exit access in buildings or areas requiring more than one exit shall be signposted. The signs shall be clearly visible at all times, where necessary supplemented by directional signs.
<p>Mid Term</p> <p><i>(The remedial works indicated must be carried out within a period of 6 weeks)</i></p>	<ul style="list-style-type: none"> • Fire license needs to be renewed by mentioning full coverage area. • Fire manager/Director need to have safety training from

Summary of Preliminary Assessment on Structural, Fire and Electrical Safety

	<p>proper authority & worker of the factory should as far as possible be trained for use fire extinguisher.</p> <ul style="list-style-type: none"> • All the exit doors need to be replaced by side swinging so that unlockable doors can be opened easily in the direction of evacuation without the use of a key. • Factory needs to provide handrail on both sides of all the stairways. • Propagation of fire, smoke, gas or fume through the opening of fire resistive floors and walls need to be restricted by sealing such opening with an approved material which needs to have a minimum 2 hours fire resistance rating of the walls. • Needs to be installed with Factory adequate illuminated emergency lighting in floor, exits and stairs. (Escape route) • Factory need to have emergency backup power for critical fire safety system with sufficient capacity & arrangement according to NTPA Guideline.
<p>Long Term</p> <p><i>(The remedial works indicated must be carried out within a period of 6 months)</i></p>	<ul style="list-style-type: none"> • Fire department pre-plan needs to be developed. • Final exit route-1 need to be protected (2 hour rated construction with 1.5 hour rated door) at each floor level entrance and need to be protected from working area and shop area at ground floor by 2 hours rated construction with 1.5 hours rated door/opening, also need to have a protected escape route till to reach safe refuse area. • Storage area need to be protected with 2 hours rated construction and 1.5 hours rated opening or doors. • Boiler: Boiler room need to be protected with 4 hours rated construction & 2 hours rated opening / door from the working floor (Iron section) of ground floor of the building. • All the stairs need to be protected with fire and smoke resistant enclosures and opening (2 hours rated enclosure and 1.5 hour rated door)and provide a protected route from all though the stairway to the final exits. • Factory need to install centralized and automatic fire detection & alarm system on all occupied floors, including other tenanted floors of the building as per

Summary of Preliminary Assessment on Structural, Fire and Electrical Safety

	<p>NTPA Guideline.</p> <ul style="list-style-type: none"> • The factory need to install manually operated electrical fire alarm system and automatic fire alarm system with single or multiple call boxes on all occupied floors, including other tenanted floors of the building. • Factory needs to install control panel for centralized automatic smoke detection & fire alarm system according to NTPA Guideline. • Factory needs to install proper standpipe system with having at least 75 mm dia of riser. • Install 1 riser per 1000 m² of floor area & Install adequate number of hose in floor area and the minimum hose diameter is 38 mm, or 1.5" preferably fabric hose with variable nozzle to be used in both of the stairways covering the floor area. • Factory need to ensure the minimum pressure for standpipes supplying a 50mm or larger hose shall be at least 300 Kpa. For standpipe supplying first aid hose (38mm nominal) may have a minimum pressure of 200 Kpa. • Factory needs to be installed with Siamese connection for to the standpipe system located outside the building and accessible to the fire department connection. • Factory needs to have dedicated fire pump with backup power system & sufficient capacity for achieve required pressure in the remote place of the factory. • Factory need to have sufficient water storage capacity to get adequate pressure to feed fire-fighting equipment and at least $1900 \times 75 = 142500$ liters water storage tank.
--	---

(B): Recommendations for Electrical Safety corrective actions:

<p>Immediate</p> <p><i>(the factory should not continue to be occupied until these non-conformities have been rectified):</i></p>	<ul style="list-style-type: none"> • Remove all unused cables from distribution boards and make sure all necessary cables are properly terminated at its point of termination using appropriate size and type of lug. • Find out the cause (improper cable/over current selection, over loading, improper lug, improper cable joints, rusted connection, insulation damage, multiple cables at single point,) of overheating (> ambient+
---	--

Summary of Preliminary Assessment on Structural, Fire and Electrical Safety

	40°C) and take proper action.
<p>Short Term</p> <p><i>(Actions that must be incorporated into a Fire Safety Management Plan immediately (a week) and should be a regular activity)</i></p>	<ul style="list-style-type: none"> • Ensure all distribution boards (including panel door) are earthed properly. • Ensure proper earthing connections at all electrical equipment. • Clean interior components from dust and debris and seal all openings within the enclosure to prevent dust and debris from entering. • Provide provision for inspection of all earthing system and ensure inspection is being completed and documented.
<p>Mid Term</p> <p><i>(The remedial works indicated must be carried out within a period of 6 weeks)</i></p>	<ul style="list-style-type: none"> • Install appropriate number and type of safety signage and fire-fighting equipment at generator room. Also ensure graded rubber mats are provided in front of all panel boards. • Provide Instruction board for first aid and artificial respiration in the generator room. • Ensure in the generator room have adequate illumination level as per standard. • Provide two separate and distinct connections of earthing for the generator. • Provide dedicated & adequate size of earthing with proper identification for each circuit from the earth bus-bar of distribution boards and ensure continuous earth path is back to main building intake. • Rewire to ensure each incoming supply to an MCB has a dedicated supply from busbar. Avoid the use of multiple cables on outgoing side of MCB's. • Replace wooden bases and panels cover with metal clad construction. • Ensure all electrical cables are sized according to capacity of circuit breakers. • Provide adequate support or mechanical guards for sewing machines. • Ensure cable joints are made in respect of conductivity, insulation and mechanical strength. • Seal the openings remaining after wiring system passes

Summary of Preliminary Assessment on Structural, Fire and Electrical Safety

	<p>through the elements of building construction according to the degree of fire resistance.</p> <ul style="list-style-type: none"> • Connect all metal in the building to the building earthing system. • Find out the cause (improper cable/over current selection, over loading, improper lug, improper cable joints, rusted connection, insulation damage, multiple cables at single point,) of overheating { ambient+(20⁰C-40⁰C)} and take proper action.
<p>Long Term</p> <p><i>(The remedial works indicated must be carried out within a period of 6 months)</i></p>	<ul style="list-style-type: none"> • Develop an electrical layout diagram and an as-built single line diagram detailing key components and capacity of the electrical system. • Establish a periodical Insulation and earth Resistance Measurement Program and record the related testing data. • Inspect electrical switchgear and panel boards on an annual basis. • Ensure overhead service connections to the building are led via adequate size and type of service masts. • Ensure appropriate generator room size in order to properly access the generator to perform routine maintenance activities. • Replace MCCB boards with metal enclosed body. • Ensure panel boards have no opening and all live internal components are concealed properly. • Provide dedicated & adequate size of neutral with proper identification for each circuit. • Ensure each distribution board is provided with a circuit list and means of identification is provided as per list. • Provide adequate covers on cable channel. • Provide proper cable terminator/connector for stranded conductors at its point of termination. • Install separate distribution boards for lighting and power circuits and lightning protection system on the building.