### Summary of Preliminary Assessment on Structural, Fire and Electrical Safety

Name of the Factory : Alliance Apparels Ltd.

Address of the Factory : "Shamsher Market" 191/1, South Bishil, Darus Salam

Road, Section-1, Mirpur, Dhaka

Present Status of the Factory : Under Operation

Structural Assessment Conducted by : BUET

Date of Structural Inspection : 25<sup>th</sup> September 2014

### **BASIC INFORMATION:**

The building that housed the present garments factory was approved by RAJUK in 1994 as 8-storied commercial cum residential building with the ground floor as the bottom most floors. The following important points were noted for the building.

(i) Building usage type: Commercial cum residential and garments factory

(ii) Structural system: Column beam frame structure.

(iii) Floor system: RC slab supported on beam columns. Typical floor heights

are 8'-08" (Clear).

(iv) Floor area: Building plan dimensions are 69'-10" × 82'-10".

Approximate floor area is 5780 sft per floor with a total

floor area of 46240 sft.

(v) No. of stories: 8 (Eight)

(vi) Construction Year: 1993-1994 (Ground to 3<sup>rd</sup> Floors) & 2004 (4<sup>th</sup> -6<sup>th</sup> Floor)

(vii) Foundation Type: Reported as isolated spread footing; Dimensions & Depth

are not known.

(viii) Design Drawings: RAJUK approved drawing, Architectural & structural

drawing & load planning were available.

(ix) Soil Investigation Report: Not available

(x) Construction Materials: Reinforced Concrete. No test reports of construction

materials were available.

• Coarse Aggregate: Brick chips

• Reinforcement: 40-grade plain steel rods

(xi) Generator: Located at ground floor

#### RECOMMENDATIONS FOR CORRECTIVE ACTION:

The recommendations of corrective action for both Structural and Fire & Electrical Safety comprises in Short Term, Mid Term and Long Term basis.

The recommendations for **Structural Safety** corrective action are:

Short Term (Immediate) : Intensity of load does not exceed 40 psf (2.0 kN/m²) at all the places of the

building. Proper measures should be taken to eradicate dampness of the

building walls.

Mid Term (6-weeks) : The factory owner has been instructed to prepare and submit a load plan of

the factory building.

Long Term (6-months) : A Detail Engineering Assessment (DEA) has to be completed. Necessary

remediation's after completion of DEA.

The recommendations for **Fire & Electrical Safety** corrective action are:

Name of the Factory : Alliance Apparels Ltd.

Fire & Electrical assessment conducted by : BUET

Date of Fire & Electrical Inspection : 20<sup>th</sup> December 2014

## **Summary of Preliminary Assessment on Structural, Fire and Electrical Safety**

### (A): Recommendations for Fire Safety corrective actions:

Fire Safety Issues	
Immediate (the factory should not continue to be occupied until these non-conformities have been rectified):	N/A
Short Term (Actions that must be incorporated into a Fire Safety Management Plan immediately (a week) and should be a regular activity	Remove all temporary obstructions from all escape routes, aisles and passageways.
	Ensure minimum width of corridors, passageways and aisles.
	Ensure monitor and maintain the same at required interval as per guidelines.
	Provide proper directional sign and exit sign in Bangla and English as per guidelines.
(The remedial works indicated must be carried out within a period of 6 weeks)	Remove temporary structure from roof top.
	Produce proper drawing and plans to create horizontal and vertical fire-rated separation for stairways of appropriate
	specifications, grills, storage and assembly areas, offices, work areas.
	Remove all collapsible gates. Produce design drawings to demonstrate how stairways are to be made of adequate dimensions and appropriate specifications and to be converted into fire-rated enclosures equipped with fire- rated side swinging doors of required dimensions opening in the direction of travel at each floor.
	Produce design to install standard standpipe, hose and fire pump system.
	Provide design to install proper detection and alarm system. Install command station as per guidelines.
	Install horizontal and vertical fire-rated separation for stairways of appropriate specifications, grills, storage and assembly areas, offices, work areas.
	Install fire rated enclosure and doors of appropriate dimensions at exit to the stairs to prevent smoke and fire propagation as per approved design.
	Install standard standpipe, hose and fire pump system. Install proper detection and alarm system.
	Provide fire rated enclosure, install self-closing fire rated door as per guidelines.

### (B): Recommendations for Electrical Safety corrective actions:

Electrical Safety Issues	
Immediate (the factory should not continue to be occupied until these non-conformities have been rectified):	N/A

# **Summary of Preliminary Assessment on Structural, Fire and Electrical Safety**

Short Term	Provide instructions for first aid and artificial respiration
(Actions that must be incorporated into a Fire Safety Management Plan immediately (a week) and should be a	from exposure to electrical shock. Provide rubber mat in front of the panel. Ensure well-dressed cabling with lugs.
regular activity	Ensure earthing of panel body & door with fitted condition.
	Provide distribution board as per guideline and put identification mark on distribution panel.
Mid Term (The remedial works indicated must be carried out within a period of 6 weeks)	Provide new Emergency Lighting system.
	Provide appropriate Lightening Protection System as per guidelines.
Long Term (The remedial works indicated must be carried out within a period of 6 months)	N/A