#### Summary of Preliminary Assessment on Structural, Fire and Electrical Safety

Name of the Factory : Tasmia Apparels Ltd. (Building-02)

Address of the Factory : 23/3, Uttar Adabor, Road # 6, Mohammadpur, Dhaka

Present Status of the Factory : Under Operation

Structural Assessment Conducted by : BUET

Date of Structural Inspection : 1<sup>st</sup> November 2014

#### **BASIC INFORMATION:**

The factory building is a 4 storied RC structure and has reinforced concrete beam-column framing system structure. The following information was noted:

i. Building Usage Type : Garment factory

ii. Fire and Electrical Safetyiii. Structural Systemiii. Structural Systemiii. Beam-Column frame system

iv. Floor System : Edge supported RC slabs (Thickness 5" approximately)

v. Floor Area : Approximately 1400 sq.ft per floor

vi. No. of Stories : 4 stories

vii. Construction Year : 2003, by Building Owner (as per verbal information)

viii. Foundation Type : Shallow footing (As per verbal information)

ix. Design Drawingsx. Soil Boring Reportix. Not availableix. Not available

xi. Construction Materials : Reinforced Concrete (with brick chips)

xii. Generator : Outside of the building

#### **RECOMMENDATIONS FOR CORRECTIVE ACTION:**

The recommendations of corrective action for both Structural and Fire & Electrical Safety comprises in Short Term, Mid Term and Long Term basis.

The recommendations for **Structural Safety** corrective action are:

Short Term (Immediate) : The factory owner has been instructed to prepare and submit a load plan for

vetting. The tin shed constructions have to be removed. As-built drawing

needs to be prepared.

Mid Term (6-weeks) : None

Long Term (6-months) : A Detail Engineering Assessment (DEA) has to be completed. Necessary

remediation's after completion of DEA.

The recommendations for Fire & Electrical Safety corrective action are:

Name of the Factory : Tasmia Apparels Ltd.

Fire & Electrical assessment conducted by : BUET

Date of Fire & Electrical Inspection : 27 October 2014

#### (A): Recommendations for Fire Safety corrective actions:

Fire Safety Issues	
Immediate (the factory should not continue to be occupied until these non-conformities have been rectified):	IN/ A

## **Summary of Preliminary Assessment on Structural, Fire and Electrical Safety**

Short Term	Remove obstructions from all escape routes, aisles and
(Actions that must be incorporated into a	<u>^</u>
Fire Safety Management Plan	Maintain minimum effective width of corridors, passageways
immediately (a week) and should be a regular activity	and aisles.
	Remove all combustible materials from boiler and generator room.
	Ensure adequate numbers of fire drills.
	Ensure that portable extinguishers are easily accessible, monitored and maintained at regular interval as per the Guidelines.
	Provide proper directional signs and exit signs in Bangla and English as per the Guidelines.
(The remedial works indicated must be carried out within a period of 6 weeks)	Remove temporary structures from roof top.
	Prepare drawings to ensure adequate horizontal and vertical fire-rated separation inside one floor and between different floors, e.g. separation with stairways, storage, work areas as per the Guidelines.
	Ensure all exit access doors are side-swinging type and open to the direction of traffic flow. Show methods to demonstrate how exit doors are to satisfy the occupancy load according to the Guideline
	Produce drawings to demonstrate how stairways are to be made of adequate dimensions and appropriate specifications and to be converted into fire-rated enclosures equipped with fire-rated doors.
	Also show methods to ensure proper separation of high risk areas (e.g., generator and boiler rooms) as per the Guidelines.
	Provide design to install standard standpipe, hose and fire pump system.
	Provide design to install proper detection and alarm system. Establish command station as per the Guidelines.
(The remedial works indicated must be carried out within a period of 6 months)	Ensure adequate horizontal and vertical fire-rated separation inside one floor and between different floors, e.g. separation with stairways, storage and work areas.
	Ensure proper separation of high risk areas (e.g., generator and boiler rooms) as per the Guidelines.
	Install standard standpipe, hose and fire pump system. Install proper detection and alarm system.
	Provide fire rated enclosure, install self-closing fire rated door as per guidelines.

### (B): Recommendations for Electrical Safety corrective actions:

Electrical Safety Issues		
Immediate (the factory should not continue to be occupied until these non-conformities have been rectified):		

# **Summary of Preliminary Assessment on Structural, Fire and Electrical Safety**

(Actions that must be incorporated into a	_
regular activity	Provide cover on the cable trench and rubber mat in front of the panel.
	Ensure well-dressed cabling with lugs and remove loose cabling.
	Ensure earthing of panel body & door with fitted condition.
	Provide distribution board as per guideline and put identification mark on distribution panel.
	Remove burn/broken/loose MCB/MCCB box/socket.
Mid Term (The remedial works indicated must be carried out within a period of 6 weeks)	Provide separate service ducts for electrical cables.
	Provide new Emergency Lighting system.
	Provide appropriate Lightening Protection System as per guidelines.
Long Term	
(The remedial works indicated must be carried out within a period of 6 months)	N/A