### Summary of Preliminary Assessment on Structural, Fire and Electrical Safety

Name of the Factory : Topaz Garments Ltd.

Address of the Factory : Hakim Tower (4th - 9th Floor), E-6, Middle Badda

Pragati Sharani Road, Dhaka - 1213

Present Status of the Factory : Under operation.

Structural Assessment Conducted by : BUET

Date of Structural Inspection : 15 June, 2014

Fire Assessment Conducted by : BUET

Date of Fire Inspection : 23 December 2014

Electrical Assessment Conducted by : BUET

Date of Electrical Inspection : 23 December 2014

BGMEA Membership No. : 1442

#### **BASIC INFORMATION:**

The following information was noted:

i. Building Usage Type : Garment Factory.

ii. Structural System

iii. Floor System

iv. Floor Area :

v. No. of Stories

vi. Construction Year

vii. Foundation Type

viii. Design Drawings

ix. Soil Investigation Report

x. Construction Materials

xi. Generator

#### RECOMMENDATIONS FOR CORRECTIVE ACTION:

The recommendations of corrective action for both Structural and Fire & Electrical Safety comprises in Short Term, Mid Term and Long Term basis.

The recommendations for **Structural Safety** corrective action are:

Short Term (Immediate) :

Mid Term (6-weeks) :

Long Term (6-months) :

The recommendations for **Fire & Electrical Safety** corrective action are:

# (A): Recommendations for Fire Safety Corrective Actions:

Immediate	N/A
(the factory should not continue to be occupied until these non-conformities have been rectified):	
Short Term	Remove obstructions from all escape routes, aisles and
(Actions that must be incorporated into a Fire Safety Management Plan immediately (1 ~ 2 weeks) and should be a regular activity	Maintain minimum effective width of corridors, passageways and aisles.
	Provide proper directional signs and exit signs in Bangla and English as per the Guidelines.
Mid Term	Remove temporary structures from roof top.
(The remedial works indicated must be carried out within a period of 6 weeks)	Prepare drawings to ensure adequate horizontal and vertical fire-rated separation inside one floor and between different floors, e.g. separation with stairways, storage, lift lobby, offices, and work areas as per the Guidelines.
	Prepare plans to ensure all exit access doors are side swinging type and open to the direction of traffic flow.
	Produce drawings to demonstrate how stairways are to be made of adequate dimensions and appropriate specifications and to be converted into fire-rated enclosures equipped with fire-rated doors.
	Also show methods to ensure proper separation of high risk areas (e.g., boiler, transformer and substation rooms) as per the Guidelines.
	Provide design to install standard standpipe, hose and fire pump system.
	Provide design to install proper detection and alarm system.
	Establish command station as per the Guidelines.
Long Term  (The remedial works indicated must be carried out within a period of 6 months)	Ensure adequate horizontal and vertical fire-rated separation inside one floor and between different floors, e.g. separation with stairways, storage, lift lobby, offices, and work areas.
	Ensure all exit access doors are side-swinging type and

Topaz Garments Ltd. Last update on Page 2

# **Summary of Preliminary Assessment on Structural, Fire and Electrical Safety**

open to the direction of traffic flow.
Ensure proper separation of high risk areas (e.g. boiler, transformer and substation rooms) as per the Guidelines.
Install standard stand pipe and hose system
Install stairways of adequate dimensions and appropriate specifications and convert into continuous fire-rated enclosures equipped with fire-rated doors.

# (B): Recommendations for Electrical Safety Corrective Actions:

Immediate	N/A
(the factory should not continue to be occupied until these non-conformities have been rectified):	
Short Term  (Actions that must be incorporated into a Fire Safety Management Plan immediately (a week) and should be a	Provide instructions for first aid and artificial respiration from exposure to electrical shock.  Provide cover on the cable trench and rubber mat in front of
regular activity	the panel.
	Ensure well-dressed cabling with lugs and remove loose cabling.
	Ensure earthing of panel body & door with fitted condition.
	Provide distribution board as per guideline and put identification mark on distribution panel.
Mid Term	Provide separate service ducts for electrical cables.
(The remedial works indicated must be carried out within a period of 6 weeks)	Provide new Emergency Lighting system.
	Provide appropriate Lightening Protection System as per guidelines.
Long Term	N/A
(The remedial works indicated must be carried out within a period of 6 months)	

Topaz Garments Ltd. Last update on Page 3