Name of the Factory : Zakaria Apparels.

Address of the Factory : Main road, Ghaatail, Tangail, Bangladesh

Present Status of the Factory : Under operation.

Structural Assessment Conducted by : VEC

Date of Structural Inspection : 11 July, 2015

Fire Assessment Conducted by : VEC

Date of Fire Inspection : 11 July, 2015

Electrical Assessment Conducted by : VEC

Date of Electrical Inspection : 11 July, 2015

BGMEA Membership No. : 5938

BASIC INFORMATION:

The factory building is a five storied RCC beam column frame system. The following information was noted:

: Garment Factory.

: RCC beam column system.

iii. Floor System : RCC Beam slab.

i. Building Usage 1,7ii. Structural Systemiii Floor System iv. Floor Area : Floor area is 14,992 sft (Total)

v. No. of Stories : 5 stories

: 2008 (Building was built in one phase). vi. Construction Year

vii. Foundation Type : Pile foundation

viii. Design Drawings : Available- Structural design drawing, soil test report,

> Not available- approval drawing, machine layout plan, architectural design drawing, material test report,

floor load plan

: Available ix. Soil Investigation Report x. Construction Materials : Brick aggregate.

: Outside the factory in a separate shed. xi. Generator

RECOMMENDATIONS FOR CORRECTIVE ACTION:

The recommendations of corrective action for both Structural and Fire & Electrical Safety comprises in Short Term, Mid Term and Long Term basis.

The recommendations for **Structural Safety** corrective action are:

Short Term (Immediate)

Mid Term (6-weeks) : 1. Building Engineer to review the adequacy of this shed. Design

should be checked by the Building Engineer to verify the lateral

stability of the shed and confirm the requirement of any

bracing in the long direction.

2. Structural engineer has to survey this factory. Prepare full set of

as built structural drawing, floor load plan and prepare

calculations showing the structural adequacy of the floor system taking into account the factory design imposed loading and the as

built structure.

Long Term (6-months) : 1. Install horizontal bracing at the roof system if required.

2. Structural engineer to prepare floor load plan showing the

structural adequacy of the floor system taking into account the factory design imposed loading and the as built structure.

3. Factory management should take approval from the proper

3. Factory management should take approval from the proper authority.

The recommendations for **Fire & Electrical Safety** corrective action are:

(A): Recommendations for Fire Safety Corrective Actions:

Immediate	N/A
(the factory should not continue to be occupied until these non-conformities have been rectified):	
Short Term (Actions that must be incorporated into a Fire Safety Management Plan immediately (1 ~ 2 weeks) and should be a regular activity	Factory needs to conduct fire drill quarterly (4 times a year) under the fire safety plan and needs to kept the written record of such drills for at least 3 years for the inspection of fire brigade whenever called for.
	Factory need to have proper testing plan & record of fire safety equipment.
	Lights in storage area needed to be installed with protective covers and conduits.
	All required means of exit or exit access in buildings or areas requiring more than one exit shall be signposted. The signs shall be clearly visible at all times, where necessary supplemented by directional signs.
	Combustibles are to be managed with good housekeeping.
	Storage facilities with no air-conditioning duct shall be minimum 2.9 m and when used as a storage facility there shall be a minimum clearance of one third the floor height from the ceiling to the top of the storage stack.
Mid Term (The remedial works indicated must be carried out within a period of 6 weeks)	Factory needs to prepare as built drawing with floor machine layout showing means of escape with proper dimension.
	All the exit doors need to be replaced by side swinging so that un-lockable doors can be opened easily in the direction of evacuation without the use of a key.
	Factory needs to provide handrail on both sides of all the stairways.
	Factory needs to be installed with adequate illuminated emergency lighting in floors, exits & stairs.(Escape route).
	Emergency back-up power needs to be connected for critical

	fire safety system and not less than 30 minutes in case of failure of power supply.
Long Term (The remedial works indicated must be carried out within a period of 6 months)	Factory needs to have a proper pre-plan for fire department. Final exit-2 need to be separated by 4 hour fire rate enclose construction and 2 hour fire rated composite door.
	Storage area need to be protected with 2 hours rated construction and 1.5 hours rated opening or doors.
	Generator room needs to be fire separated with 4 hours fire rated enclosure and 2 hour rated opening.
	Boiler & compressor room needs to be fire separated with 4 hours fire rated enclosure and 2 hour rated opening.`
	All the exits connecting to the staircase need to be protected with fire and smoke resistant enclosures and opening (2 hours rated enclosure and 1.5 hour rated door) and provide a protected route from all though the stairway to the final exits.
	Factory need to install centralized and automatic fire detection & alarm system on all occupied floors, including other tenanted floors of the building as per NTPA Guideline.
	The factory need to install manually operated electrical fire alarm system and automatic fire alarm system with single or multiple call boxes on all occupied floors, including other tenanted floors of the building.
	Factory needs to install control panel for centralized automatic smoke detection & fire alarm system according to NTPA Guideline.
	Install proper standpipe system having at least 75 mm dia of standpipe.
	Install 1 riser per 1000 m2 of floor area & Install adequate number of hose in floor area and the minimum hose diameter is 38 mm, or 1.5" preferably fabric hose with variable nozzle to be used in both of the stairways covering the floor area.
	Factory need to ensure the minimum pressure for standpipes supplying a 50mm or larger hose shall be at least 300 Kpa. For standpipe supplying first aid hose (38mm nominal) may have a minimum pressure of 200 Kpa.
	Factory needs to be installed with Siamese connection for to the standpipe

system located outside the building and accessible to the fire department connection.
Factory needs to have dedicated fire pump with backup power system & sufficient capacity for achieve required pressure in the remote place of the factory.
Factory need to have sufficient water storage capacity to get adequate pressure to feed fire-fighting equipment and at least $1900 \times 75 = 142500$ liters water storage tank

(B): Recommendations for Electrical Safety Corrective Actions:

Immediate (the factory should not continue to be occupied until these non-conformities have been rectified):	Find out the cause (improper cable/over current selection, over loading, improper lug, improper cable joints, rusted connection, insulation damage, multiple cables at single point,) of overheating (> ambient+ 40°C) and take proper action
Short Term (Actions that must be incorporated into a Fire Safety Management Plan immediately (a week) and should be a regular activity	Ensure all panel boards (including panel door) are earthed properly. Remove all unused cables from distribution boards and make sure all necessary cables are properly terminated at its point of termination using appropriate size and type of lug. Ensure overcurrent protection device (circuit breaker/fuse) for each circuit or branch circuit. Ensure proper earthing connections at all electrical equipment's. Clean interior components from dust and debris and seal all openings within the enclosure to prevent dust and debris from entering. Ensure inspection of all earthing system is being completed and documented.
Mid Term (The remedial works indicated must be carried out within a period of 6 weeks)	Ensure appropriate type of safety signage and graded rubber mats at required location. Provide Instruction board for first aid and artificial respiration in the generator room. Provide two separate and distinct connections of earthing for the generator. Provide dedicated & adequate size of earthing with proper

identification for each circuit and ensure continuous earth path is back to main building intake. Rewire to ensure each incoming supply to an MCB has a dedicated supply from busbar. Avoid the use of multiple cables on outgoing side of MCB's. Replace wooden base with metal clad construction for mounting circuit breaker and fuse. Ensure all electrical cables are sized according to capacity of circuit breakers. Avoid flexible cables for fixed wiring unless contained in an enclosure affording mechanical protection. Ensure cable joints are made in respect of conductivity, insulation and mechanical strength. Connect all metal in the building to the building earthing system. Long Term Update as-built single line diagram detailing key components and capacity of the electrical system. (The remedial works indicated must be carried out within a period of 6 months) Establish a periodical Insulation and earth Resistance Measurement Program and record the related testing data. Inspect electrical panel boards on an annual basis. Ensure the generator room has adequate fire separation from the production area. Provide adequate means of ventilation for the generator room based on the installed equipment considering fire barriers. Ensure panel boards have no opening and all live internal components are concealed properly. Provide dedicated & adequate size of neutral with proper identification for each applicable circuit. Ensure each distribution board is provided with a circuit list and means of identification is provided as per list. Provide adequate support or mechanical guards for electrical wiring where necessary.

Provide adequate covers on cable channel.
Provide proper cable terminator/connector for stranded conductors at its point of termination.
Install separate distribution boards for lighting and power circuits.
Install lightning protection system on the building