

Summary of Preliminary Assessment on Structural, Fire and Electrical Safety

Name of the Factory	: The Chittagong Fashion Ltd.
Address of the Factory	: Khawja Complex, CB -234/9, Kachukhet, Dhaka Cant, Dhaka 1206
Present Status of the Factory	: Under operation.
Structural Assessment Conducted by	:
Date of Structural Inspection	:
Fire Assessment Conducted by	: BUET
Date of Fire Inspection	: 20 October 2014
Electrical Assessment Conducted by	: BUET
Date of Electrical Inspection	: 20 October 2014
BGMEA Membership No.	: 3620

BASIC INFORMATION:

The following information was noted:

- i. Building Usage Type : Garment Factory.
- ii. Structural System :
- iii. Floor System :
- iv. Floor Area :
- v. No. of Stories :
- vi. Construction Year :
- vii. Foundation Type :
- viii. Design Drawings :
- ix. Soil Investigation Report :
- x. Construction Materials :
- xi. Generator :

RECOMMENDATIONS FOR CORRECTIVE ACTION:

The recommendations of corrective action for both Structural and Fire & Electrical Safety comprises in Short Term, Mid Term and Long Term basis.

The recommendations for **Structural Safety** corrective action are:

- | | |
|------------------------|---|
| Short Term (Immediate) | : |
| Mid Term (6-weeks) | : |
| Long Term (6-months) | : |

Summary of Preliminary Assessment on Structural, Fire and Electrical Safety

The recommendations for **Fire & Electrical Safety** corrective action are:

(A): Recommendations for Fire Safety Corrective Actions:

<p>Immediate</p> <p><i>(the factory should not continue to be occupied until these non-conformities have been rectified):</i></p>	<p>N/A</p>
<p>Short Term</p> <p><i>(Actions that must be incorporated into a Fire Safety Management Plan immediately (1 ~ 2 weeks) and should be a regular activity</i></p>	<p>Remove obstructions from all escape routes, aisles and passageways.</p> <p>Maintain minimum effective width of corridors, passageways and aisles.</p> <p>Remove all combustibile materials from transformer, substation, boiler and generator room, if exists.</p> <p>Confirm adequate numbers of fire drills.</p> <p>Make sure that portable extinguishers are easily accessible, monitored and maintained at regular interval as per the Guidelines.</p> <p>Provide proper directional signs and exit signs in Bangla and English as per the Guidelines.</p>
<p>Mid Term</p> <p><i>(The remedial works indicated must be carried out within a period of 6 weeks)</i></p>	<p>Remove temporary structures from roof top.</p> <p>Prepare drawings to ensure adequate horizontal and vertical fire-rated separation inside one floor and between different floors, e.g. separation with stairways, storage, and basement, lift lobby, offices, and work areas as per the Guidelines.</p> <p>Prepare plans to ensure all exit access doors are side swinging type and open to the direction of traffic flow.</p> <p>Produce drawings to demonstrate how stairways are to be made of adequate dimensions and appropriate specifications and to be converted into fire-rated enclosures equipped with fire-rated doors.</p> <p>Also show methods to ensure proper separation of high risk areas (e.g., generator, boiler, transformer and substation rooms) as per the Guidelines.</p> <p>Provide design to install standard standpipe, hose and fire pump system.</p>

Summary of Preliminary Assessment on Structural, Fire and Electrical Safety

	<p>Provide design to install proper detection and alarm system.</p> <p>Establish command station as per the Guidelines.</p>
<p>Long Term</p> <p><i>(The remedial works indicated must be carried out within a period of 6 months)</i></p>	<p>Ensure adequate horizontal and vertical fire-rated separation inside one floor and between different floors, e.g. separation with stairways, storage, assembly areas, basement, lift lobby, offices, and work areas.</p> <p>Ensure proper separation of high risk areas (e.g., generator, boiler, transformer and substation rooms) as per the Guidelines.</p> <p>Ensure all exit access doors are side-swinging type and open to the direction of traffic flow.</p> <p>Install standard standpipe, hose and fire pump system. Install proper detection and alarm system.</p> <p>Provide fire rated enclosure, install self-closing fire rated door as per guidelines.</p>

(B): Recommendations for Electrical Safety Corrective Actions:

<p>Immediate</p> <p><i>(the factory should not continue to be occupied until these non-conformities have been rectified):</i></p>	N/A
<p>Short Term</p> <p><i>(Actions that must be incorporated into a Fire Safety Management Plan immediately (a week) and should be a regular activity)</i></p>	<p>Provide instructions for first aid and artificial respiration from exposure to electrical shock.</p> <p>Provide cable trench with and rubber mat in front of the panel.</p> <p>Ensure well-dressed cabling with lugs and remove loose cabling.</p> <p>Ensure earthing of panel body & door with fitted condition.</p> <p>Provide distribution board as per guideline and put identification mark on distribution panel.</p> <p>Remove burn/broken/loose MCB/MCCB box/socket.</p>

Summary of Preliminary Assessment on Structural, Fire and Electrical Safety

Mid Term <i>(The remedial works indicated must be carried out within a period of 6 weeks)</i>	Provide separate service ducts for electrical cables. Provide new Emergency Lighting system. Provide appropriate Lightening Protection System as per guidelines.
Long Term <i>(The remedial works indicated must be carried out within a period of 6 months)</i>	N/A